
ASSEMBLY

Watson Pin & Tak Deskmount Acrylic Screen



Acrylic Deskmount Screen Basic Components




Hardware








Square Drive Thread Cutting Screw #8x1 3/4" (0000238)



5/18-18x1"Clamping Screw (0000229)

Tools



Electric Drill





Phillips Drill/Driver Bit






2mm Hex Drill/Driver Bit



3mm Hex Drill/Driver Bit






 ${\tt Additional\ tools\ such\ as\ a\ 90\ Degree\ Bit\ and\ an\ 18"\ Extension\ are\ helpful\ for\ some\ steps}$


*No torque or ball bits should be used

1. Position Medallions

Press Medallion plates into holes in acrylic until flush. Consult visual to determine orientation for Desk and Side Screen.

NOTE: Medallion orientation depends on Screen type







2. Secure Brackets

Position mountion brackets onto the studs sticking through the board and secure into place with nylon-lock nuts (090770).




¼-20 Lock Nut, Zinc (090770)






3. Insert Clamping Screw

For 90 edges, the clamping screw (0000229) can be attached by screwing into the threaded hole on the back internal of the bracket. The screw should have atleast 3/4" clearance from top of bracket.



5/18-18x1"Clamping Screw (0000229)



4. Attaching to Desk

Slide screen onto desk until bracket is flush with edge. If a 90 Edge, tighten clamping screw upp against underside of desk. If a knife edge, screw wood screws (0000238) through front two holes into top.



Square Drive Thread Cutting Screw #8x1 3/4" (0000238)

